




Note: Aerial Photography By
Science Applications International Corporation (SAIC)
April, 1998

Paseo de Las Iglesias Geotechnical Report



Pima County Technical Services
201 North Stone Avenue - 9th Floor
Tucson, Arizona 85701-1207
(520)740-6670 - FAX:(520)798-3429
<http://www.dot.co.pima.az.us>

The information depicted on this display is the result of digital analysis performed on a variety of databases provided and maintained by several governmental agencies. The accuracy of the information presented is limited to the collective accuracy of these databases on the date of the analysis. The Pima County Department of Transportation Technical Services Division makes no claims regarding the accuracy of the information depicted herein.

This product is subject to the Department of Transportation Technical Services Division's Use Restriction Agreement.

- Washes
- Study Area
- Township and Range
- Section Lines
- ADWR Well Locations
- Sediment Sampling Locations

